

www.carchecknz.co.nz

10 Jul 2024 / HVS

Complete

Flagged items	0
Inspection Date	10.07.2024
Inspectors Name	Damien
Buyers name	HVS
Buyers Phone Number	0000000
Buyers Email	000000000
Make	Nissan
Model	Xtrail
VIN #	7atodh6lx2409952
Plate	None
KMS	87348
Fuel Type	Petrol
Engine Size	2000cc
WOF Expiry Date	02.07.2025
Service Interval	97000km
Registration Date	

Page 2: Vehicle Pre-Purchase Inspection

Body Report

Condition

Good

Right Hand Side



Photo 1

Rear



Photo 2

Left Hand Side



Photo 3

Front



Photo 4

Interior



Photo 5

General Body Condition

Tidy condition for age and kms

Mechanical Report

Tyres

Good



Photo 6

Wheel Condition

Good

Suspension

Good

Steering

Good

Exhaust System

Good

CVs

Good

Driveshaft

Good

Brakes

Good

Heater

Good

Air Conditioning

Good

Engine

Good

Cooling System

Good

Visible Oil Leaks

Good

Drive Belts

Good

Cambelt Evidence

N/A

Fluid levels

Pass

Trans/Gear Box

Good

Road Test

Pass

Battery (12v)

Pass

Wiper/Washers

Pass

Horn	Pass
Windows Operation	Pass
Central Locking	Pass
Remote Key	Pass
Two keys	
	
Photo 7	
Lights	Pass
Mirrors Operation	Pass
Comments	
Tidy overall condition	
Interior Report	
Seatbelts	Good
Stereo	Good
Japanese with band expander	
Seats	Good
Dashboard	Good
Roof Lining	Good
Engine Management System	
Dash Warning Lights	Pass
DTC Codes if selected	N/A
Hybrid/Ev Battery SOH Report if selected	
Completed	
Signed	



10.07.2024 09:54 NZST

Disclaimer

This is a visual, non-mechanical inspection only. Vehicle components will not be removed from the vehicle during the inspection. You acknowledge that while the inspectors use accepted methods for fault detection, these methods may not identify all faults. The inspection includes the vehicles Body, Interior, Exterior, Electrical Systems, Engine systems, Cooling Systems, Exhaust Systems, Braking Systems, Fuel Systems, Steering & Suspension Systems, Safety Systems, Transmission Systems, Final Drive Systems, Chassis, Understructure and a Road test, where possible.

The representative or company carrying out the inspection will not be responsible for defects found before or after the inspection is carried out, items may not be visually identifiable at the time of inspection.

The inspection is only current as at the time and date of issue. It is not a roadworthy certificate and cannot be used as one. Inspectors are not required to follow up manufacturer recall notices. The inspection is visual verification against the vehicle condition at the time of inspection. It is buyer\'s responsibility to assess the vehicle at the point of sale.

The representative or company will not be responsible for the terms of any agreement or transaction or conversations between any persons in relation to any vehicle inspected. The representative or company will not be responsible for resolving disputes between parties in relation to any transactions.

Subject to all applicable laws, the representative or company does not provide any guarantee, warranty or representation regarding the nature, reliability, accuracy or completeness of any information contained in the inspection or the fitness of the information contained in the inspection for any purpose intended.

The representative or company will not be liable to you for loss of use, production, profit, revenue, business, data, contractor anticipated savings or for delay or for any financing costs or increase in operating costs or any economic loss for any indirect or consequential loss or damage.

Media summary



Photo 1



Photo 2



Photo 3



Photo 4



Photo 5



Photo 6



Photo 7